

URGENT PRODUCT RECALL



AVANTI "DERELIKT" TYPE 1, TYPE 2 AND TYPE 3 MODEL BICYCLES

Defect & potential hazard:

Sheppard Industries is conducting a voluntary consumer level recall on the above products due to the possibility that the head tube may be prone to cracking when used in certain circumstances.

In the interests of public safety, Sheppard Industries is conducting a voluntary recall of all potentially affected bicycles pending further investigations.

Models affected:

The following bicycles in the Avanti "Derelikt" range are affected:

- 2006 – Derelikt 1, 2 and 3 models (serial number U5+)
- 2007 – Derelikt 1, 2 and 3 models (serial number U6+)
- 2008 – Derelikt 1, 2 and 3 models (serial number U7+)

The serial numbers can be found under the bottom bracket shell of the frame.

The affected bicycles were available for retail sale from 1 July 2005.

What to do:

Consumers should stop riding the bicycles immediately and contact their place of purchase to arrange for a replacement frame to be ordered and delivered to the place of purchase for refitting. All affected models will be replaced with a 2011 ABD Flow aluminium frame. Replacement frames are expected to arrive in store by mid July. You will be contacted when the frames arrive in store to arrange a time for fitting. The replacement frame will be fitted at Sheppard Industries' cost.

This recall has been undertaken to ensure the safety of our customers as an ongoing commitment to maintain the highest possible standards of safety and product enjoyment at all times.

Contact details:

Sheppard Industries
25 Levene Place, Mt Wellington, Auckland

P: 0800 999 499

E: nzrecall@avantibikes.co.nz